A1




The Contractor is to check and verify all building and site dimensions, levels and sewer invert levels at connection points before work starts. The Contractor is to comply in all respects with current Building Legislation, British Standard Specifications , Building Regulations, Construction (Design & Management) Regulations, Party Wall Act, etc whether or not specifically stated on this drawing. This drawing must be read with and checked against any structural, geotechnical or other specialist documentation provided. This drawing is not intended to show details of foundations, ground conditions or ground contaminants. Each area of ground relied upon to support any structure depicted (including drainage) must be investigated by the Contractor. A suitable method of foundation should be provided allowing for existing ground conditions. Any suspect or fluid ground, contaminants on or within the ground, should be further investigated by a suitable expert. Any earthwork constructions shown indicate typical slopes for guidance only & should be further investigated by a suitable expert.

Where existing trees are to be retained they should be subject to a full Arboricultural Inspection for safety. All trees are to be planted so as ensure they are a minimum of 5 metres from buildings and 3 metres from drainage and services. A suitable method of foundation is to be provided to accommodate the proposed tree planting.

Geoff Parry Associates Limited do not accept any responsibility for any losses (financial or otherwise) to any Client or third party arising out of the Clients (be it Developer or Contractor but not limited thereto) non-compliance with afore mentioned provisos.



This survey has been orientated to the Ordnance Survey (O.S) National Grid (OSGB36) via a Global Position System (GPS) and the O.S. Active Network (OS Net).

A true OSGB36 coordinate has been established near to the site centre via a transformation using the OSTN02 & OSGM02 transformation models. The survey has been correlated to this point and a further one or more OSGB36 points established to create a true O.S. bearing for angle orientation.

No scale factor has been applied to the survey therefore the coordinates shown are arbitrary & not true O.S. Coordinates which have a scale factor applied.

Please refer to Survey Station Table to enable establishment of the on-site grid.

3D information frozen on layer TRIANGLES

**Scale Check:**

1:20 - 0 200mm 400mm 600mm 800mm 1000 1200
1:100 - 0 1m 2m 3m 4m 5m 6m
1:50 - 0 1m 2m 3m 4m 5m 6m
1:5 - 0 100mm 200mm 300mm 400mm

**Revisions:**

Rev A; additional information added to nothern boundary. June 14

**Client:** Investin PLC

**Project:** Coventry Stadium, Coventry

**Title:** Site Survey 2 of 2

**Date:** June 2014 **Scale:** 1:500 @ A1
**Drawn by:** DW **Checked by:** ICP

| Job No. | Drwg No. | Rev. |
|---|---|---|
| S 219 | 447 | A |

SURVEYING
The Shrubbery, 28 Erdington Road, Aldridge, Walsall, WS9 8UH
t 01922 744900 f 01922 744901
enquiries@geoffperryassoc.co.uk

# APPENDIX C


## Sewer Node / Sewer Pipe Data

| REFERENCE | COVER LEVEL | INV LEVEL UPSTR | INV LEVEL DOWNSTR | PURP | MATL | SHAPE | MAX SIZE | MIN SIZE | GRADIENT | YEAR LAID |
|---|---|---|---|---|---|---|---|---|---|---|
| SP40771102 | 95.06 | 94.18 | 93.53 | S | VC | C | 225 | nil | 143.03 | nill |
| SP40771204 | 94.28 | 93.35 | 93.23 | S | nil | C | 150 | nil | 195.08 | nill |
| SP40771206 | 94.53 | 93.42 | 92.89 | F | nil | C | 150 | nil | 33.58 | nill |
| SP40771209 | 94.63 | 93.17 | 93.09 | S | nil | C | 225 | nil | 374.63 | nill |
| SP40771211 | 94.60 | 93.07 | 92.85 | F | nil | C | 150 | nil | 144.45 | nill |
| SP40771216 | 94.79 | 93.23 | 93.09 | F | nil | C | 150 | nil | 246.71 | nill |
| SP40771217 | 94.90 | 93.39 | 93.26 | F | nil | C | 150 | nil | 49.23 | nill |
| SP40771218 | 94.94 | 93.61 | 93.53 | S | nil | C | 225 | nil | 35.38 | nill |
| SP40771219 | 94.76 | 93.48 | 93.19 | S | VC | C | 225 | nil | 126.52 | nill |
| SP40771220 | 94.91 | 93.63 | 93.41 | F | nil | C | 150 | nil | 119.32 | nill |
| SP40771221 | 94.93 | 93.94 | 93.63 | S | nil | C | 225 | nil | 101.03 | nill |
| SP40771301 | 94.57 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40772201 | 95.22 | 93.94 | 93.65 | F | nil | C | 150 | nil | 139.30 | nill |
| SP40772202 | 95.21 | 94.20 | 93.99 | S | nil | C | 225 | nil | 207.90 | nill |
| SP40772301 | 94.72 | 92.48 | 91.53 | F | nil | C | 225 | nil | 212.14 | nill |
| SP40772302 | 94.77 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40773201 | 94.97 | 92.80 | 92.50 | F | nil | C | 225 | nil | 281.68 | nill |
| SP40773202 | 94.92 | 93.08 | 92.82 | F | nil | C | 225 | nil | 269.68 | nill |
| SP40773203 | 95.08 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40773301 | 94.86 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40774201 | 95.36 | 93.98 | 93.74 | F | nil | C | 150 | nil | 80.04 | nill |
| SP40774202 | 95.30 | 93.72 | 93.10 | F | nil | C | 150 | nil | 136.34 | nill |
| SP40775101 | 95.92 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40775102 | nil | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40775103 | 96.00 | 94.67 | 94.00 | F | nil | C | 150 | nil | 155.99 | nill |
| SP40775104 | 96.31 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| nil | nil | nil | nil | F | nil | nil | nil | nil | 0.00 | nill |
| nil | nil | nil | nil | F | nil | nil | nil | nil | 0.00 | nill |
| nil | nil | nil | nil | F | nil | nil | nil | nil | 0.00 | nill |
| nil | nil | nil | nil | F | nil | nil | nil | nil | 0.00 | nill |
| nil | nil | nil | nil | F | nil | nil | nil | nil | 0.00 | nill |

- Abandoned Gravity Sewer
- Private Combined Gravity Sewer
- Private Foul Gravity Sewer
- Private Surface Water Gravity Sewer
- Public Combined Gravity Sewer
- Public Foul Gravity Sewer
- Public Surface Water Gravity Sewer
- Trunk Combined Gravity Sewer
- Trunk Foul Use Gravity Sewer
- Trunk Surface Water Gravity Sewer
- Combined Use Pressurised Sewer
- Foul Use Pressurised Sewer
- Surface Water Pressurised Sewer
- Highway Drain
- Combined Lateral Drain (SS)
- Foul Lateral Drain (SS)
- Surface Water Lateral Drain (SS)

All Private Sewers are shown in magenta
All section 104 sewers are shown in green

- Culverted Watercourse
- Cable, Earthing
- Cable Junction
- Cable, Optical Fibre/Instrumentation
- Cable, Low Voltage
- Cable, High Voltage
- Cable, Other
- Housing, Building
- Housing, Kiosk
- Disposal Site
- Sewage Treatment Works
- Housing, Other
- Pipe Support Structure
- Sewage Pumping Facility
- Sewer Facility Connection Inlet / Outlet

- Blind Shaft
- Combined Use Manhole
- Flushing Chamber
- Foul Use Manhole
- Grease Trap
- Head Node
- Hydrobrake
- Lamphole
- Outfall
- Overflow
- Penstock
- Petrol Interceptor

- Sewer Chemical Injection Point
- Sewer Junction
- Sewerage Air Valve
- Sewerage Hatch Box Point
- Sewerage Isolation Valve
- Soakaway
- Surface Water Manhole
- Vent Column
- Waste Water Storage
- Pre-1937 Properties

**TABULAR KEY**

**A. Sewer pipe data refers to downstream sewer pipe.**

**B. Where the node bifurcates (splits) X and Y indicates downstream sewer pipe.**

**C. Gradient is stated a 1 in...**

**MATERIALS**

- - NONE
- AC - ASBESTOS CEMENT
- BR - BRICK
- CC - CONCRETE BOX CULVERT
- CI - CAST IRON
- CO - CONCRETE
- CSB - CONCRETE SEGMENTS (BOLTED)
- CSU - CONCRETE SEGMENTS (UNBOLTED)
- DI - DUCTILE IRON
- GRC - GLASS REINFORCED CONCRETE
- GRP - GLASS REINFORCED PLASTIC
- MAC - MASONRY IN REGULAR COURSES
- MAR - MASONRY RANDOMLY COURSED
- PE - POLYETHLENE
- PF - PITCH
- PP - POLYPROPYLENE
- PSC - PLASTIC STEEL COMPOSITE
- PVC - POLYVINYL CHLORIDE
- RPM - REINFORCED PLASTIC MATRIX
- SI - SPUN (GREY) IRON
- ST - STEEL
- U - UNKNOWN
- VC - VITRIFIED CLAY
- XXX - OTHER

**SHAPE**

- C - CIRCULAR
- E - EGG SHAPED
- O - OTHER
- R - RECTANGLE
- S - SQUARE
- T - TRAPEZOIDAL
- U - UNKNOWN

**PURPOSE**

- C - COMBINED
- E - FINAL EFFLUENT
- F - FOUL
- L - SLUDGE
- S - SURFACE WATER

**CATEGORIES**

N / W / E / S

- W - WEIR
- C - CASCADE
- DB - DAMBOARD
- SE - SIDE ENTRY
- FV - FLAP VALVE
- BD - BACK DROP
- S - SIPHON
- HD - HIGHWAY DRAIN
- S104 - SECTION 104


SEVERN TRENT WATER

**Severn Trent Water Limited**
**Asset Data Management**
**PO Box 5344**
**Coventry**
**CV3 9FT**
**Telephone: 0845 601 6616**


# SEWER RECORD (Tabular)

| | | | |
|---|---|---|---|
| **O/S Map scale:** | 1:2500 | **This map is centred upon: O / S Grid reference:** | |
| **Date of Issue:** | 29.08.14 | **x :** | 440345 |
| **Sheet No.** | 1 of 1 | **y :** | 277286 |




## Sewer Node / Sewer Pipe Data

| REFERENCE | COVER LEVEL | INV LEVEL UPSTR | INV LEVEL DOWNSTR | PURP | MATL | SHAPE | MAX SIZE | MIN SIZE | GRADIENT | YEAR LAID |
|---|---|---|---|---|---|---|---|---|---|---|
| SP40767901 | 95.53 | 93.12 | 92.27 | F | VC | C | 150 | nil | 76.02 | nill |
| SP40767902 | 95.64 | 93.16 | 93.13 | F | VC | C | 150 | nil | 906.67 | nill |
| SP40775101 | 95.92 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40775102 | nil | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40775103 | 96.00 | 94.67 | 94.00 | F | nil | C | 150 | nil | 155.99 | nill |
| SP40775104 | 96.31 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40776001 | 96.46 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40776002 | 96.36 | nil | nil | nil | nil | nil | nil | nil | 0.00 | nill |
| SP40777002 | nil | nil | 93.17 | F | VC | C | 150 | nil | 0.00 | nill |
| SP40778101 | 96.61 | 95.90 | nil | F | VC | C | 100 | nil | 0.00 | nill |
| SP40778102 | nil | nil | 94.88 | F | VC | C | 150 | nil | 0.00 | nill |
| SP40778103 | 96.57 | 94.82 | nil | F | VC | C | 150 | nil | 0.00 | nill |
| SP40778104 | nil | nil | nil | F | VC | C | 150 | nil | 0.00 | nill |

- Abandoned Gravity Sewer
- Private Combined Gravity Sewer
- Private Foul Gravity Sewer
- Private Surface Water Gravity Sewer
- Public Combined Gravity Sewer
- Public Foul Gravity Sewer
- Public Surface Water Gravity Sewer
- Trunk Combined Gravity Sewer
- Trunk Foul Use Gravity Sewer
- Trunk Surface Water Gravity Sewer
- Combined Use Pressurised Sewer
- Foul Use Pressurised Sewer
- Surface Water Pressurised Sewer
- Highway Drain
- Combined Lateral Drain (SS)
- Foul Lateral Drain (SS)
- Surface Water Lateral Drain (SS)

All Private Sewers are shown in magenta
All section 104 sewers are shown in green

- Culverted Watercourse
- Cable, Earthing
- Cable Junction
- Cable, Optical Fibre/Instrumentation
- Cable, Low Voltage
- Cable, High Voltage
- Cable, Other
- Housing, Building
- Housing, Kiosk
- Disposal Site
- Sewage Treatment Works
- Housing, Other
- Pipe Support Structure
- Sewage Pumping Facility
- Sewer Facility Connection Inlet / Outlet

- Blind Shaft
- Combined Use Manhole
- Flushing Chamber
- Foul Use Manhole
- Grease Trap
- Head Node
- Hydrobrake
- Lamphole
- Outfall
- Overflow
- Penstock
- Petrol Interceptor

- Sewer Chemical Injection Point
- Sewer Junction
- Sewerage Air Valve
- Sewerage Hatch Box Point
- Sewerage Isolation Valve
- Soakaway
- Surface Water Manhole
- Vent Column
- Waste Water Storage
- Pre-1937 Properties

**TABULAR KEY**

**Sewer pipe data refers to downstream sewer pipe.**
**Where the node bifurcates (splits) X and Y indicates downstream sewer pipe.**
**Gradient is stated a 1 in...**

A.
B.
C.

### MATERIALS

- - NONE
AC - ASBESTOS CEMENT
BR - BRICK
CC - CONCRETE BOX CULVERT
CI - CAST IRON
CO - CONCRETE
CSB - CONCRETE SEGMENTS (BOLTED)
CSU - CONCRETE SEGMENTS (UNBOLTED)
DI - DUCTILE IRON
GRC - GLASS REINFORCED CONCRETE
GRP - GLASS REINFORCED PLASTIC
MAC - MASONRY IN REGULAR COURSES
MAR - MASONRY RANDOMLY COURSED
PE - POLYETHLENE
PF - PITCH
PP - POLYPROPYLENE
PSC - PLASTIC STEEL COMPOSITE
PVC - POLYVINYL CHLORIDE
RPM - REINFORCED PLASTIC MATRIX
SI - SPUN (GREY) IRON
ST - STEEL
U - UNKNOWN
VC - VITRIFIED CLAY
XXX - OTHER

### SHAPE

C - CIRCULAR
E - EGG SHAPED
O - OTHER
R - RECTANGLE
S - SQUARE
T - TRAPEZOIDAL
U - UNKNOWN

### PURPOSE

C - COMBINED
E - FINAL EFFLUENT
F - FOUL
L - SLUDGE
S - SURFACE WATER

### CATEGORIES

W - WEIR
C - CASCADE
DB - DAMBOARD
SE - SIDE ENTRY
FV - FLAP VALVE
BD - BACK DROP
S - SIPHON
HD - HIGHWAY DRAIN
S104 - SECTION 104


SEVERN TRENT WATER

**Severn Trent Water Limited**
**Asset Data Management**
**PO Box 5344**
**Coventry**
**CV3 9FT**
**Telephone: 0845 601 5616**


# SEWER RECORD (Tabular)

| | | | |
|---|---|---|---|
| **O/S Map scale:** | 1:2500 | **This map is centred upon: O / S Grid reference:** | |
| **Date of Issue:** | 29.08.14 | **x :** | 440732 |
| **Sheet No.** | 1 of 1 | **y :** | 277181 |

# APPENDIX D

The scaling of this drawing cannot be assured

| Revision | | Date | Drn | Ckd |
|---|---|---|---|---|
| C | Site Boundary updated to reflect dwg 9000-Rev B | 14.12.17 | EMB | CDB |

Gossett Lane

Gossett Lane

A428-Rugby Road

Speedway Lane

LEGEND

- Site boundary
- Primary vehicular access point
- Pedestrian access point
- Residential development
- Potential location for single storey development
- Indicative location of proposed new dwelling on Rugby Road
- Retained access to new dwelling and existing properties on Rugby Road (front and rear access as appropriate)
- Public Open space
- Existing tree/ hedgerow planting
- New trees/ hedgerow planting
- Proposed area for attenuation
- Foul pump station
- Area for formal play
- Informal pedestrian footpath
- Mown path
- Existing PROW- Footpath
- Existing PROW- Bridleway
- Existing PROW- Twelve O'Clock Ride

N

Project
Brandon Stadium
Coventry

Drawing Title
Illustrative Masterplan

| Date | Scale | Drawn by | Check by |
|---|---|---|---|
| 24.08.17 | 1:1000 @ A1 | EMB | JdH |
| Project No | Drawing No | | Revision |
| 27510 | 9401 | | C |

BARTON WILLMORE

Planning • Master Planning & Urban Design • Architecture • Landscape Planning & Design • Environmental Planning • Graphic Communication • Public Engagement • Development Economics

bartonwillmore.co.uk

Offices in Birmingham, Bristol, Cambridge, Cardiff, Edinburgh, Glasgow, London, Manchester, Newcastle, Reading and Southampton



J:\27500 - 27999\27510 - Brandon Stadium, Coventry\A1 - Dwg & Reports\Master Planning\Drawings\27510 9401 Illustrative Masterplan Rev C.dwg - A1

# APPENDIX E

## ICP SUDS Mean Annual Flood

Input

| | | | |
|---|---|---|---|
| Return Period (years) | 100 | Soil | 0.450 |
| Area (ha) | 4.150 | Urban | 0.000 |
| SAAR (mm) | 700 | Region Number | Region 4 |

**Results l/s**

| | |
|---|---|
| QBAR Rural | 18.2 |
| QBAR Urban | 18.2 |
| Q100 years | 46.9 |
| Q1 year | 15.1 |
| Q30 years | 35.7 |
| Q100 years | 46.9 |

## Summary of Results for 100 year Return Period (+40%)

| Storm Event | Max Level (m) | Max Depth (m) | Max Control (l/s) | Max Volume (m³) | Status |
|---|---|---|---|---|---|
| 15 min Summer | 100.470 | 0.470 | 7.6 | 305.5 | O K |
| 30 min Summer | 100.590 | 0.590 | 7.6 | 398.8 | O K |
| 60 min Summer | 100.703 | 0.703 | 7.6 | 491.9 | O K |
| 120 min Summer | 100.801 | 0.801 | 8.1 | 578.2 | O K |
| 180 min Summer | 100.848 | 0.848 | 8.4 | 620.2 | O K |
| 240 min Summer | 100.873 | 0.873 | 8.5 | 643.0 | O K |
| 360 min Summer | 100.893 | 0.893 | 8.6 | 662.2 | O K |
| 480 min Summer | 100.898 | 0.898 | 8.6 | 666.4 | O K |
| 600 min Summer | 100.893 | 0.893 | 8.6 | 661.8 | O K |
| 720 min Summer | 100.886 | 0.886 | 8.6 | 655.9 | O K |
| 960 min Summer | 100.872 | 0.872 | 8.5 | 642.2 | O K |
| 1440 min Summer | 100.838 | 0.838 | 8.3 | 610.9 | O K |
| 2160 min Summer | 100.783 | 0.783 | 8.0 | 561.9 | O K |
| 2880 min Summer | 100.730 | 0.730 | 7.8 | 515.6 | O K |
| 4320 min Summer | 100.631 | 0.631 | 7.6 | 432.2 | O K |
| 5760 min Summer | 100.540 | 0.540 | 7.6 | 358.7 | O K |
| 7200 min Summer | 100.451 | 0.451 | 7.6 | 291.1 | O K |
| 8640 min Summer | 100.353 | 0.353 | 7.6 | 220.6 | O K |
| 10080 min Summer | 100.262 | 0.262 | 7.6 | 158.5 | O K |
| 15 min Winter | 100.519 | 0.519 | 7.6 | 342.7 | O K |
| 30 min Winter | 100.650 | 0.650 | 7.6 | 447.5 | O K |

| Storm Event | Rain (mm/hr) | Flooded Volume (m³) | Discharge Volume (m³) | Time-Peak (mins) |
|---|---|---|---|---|
| 15 min Summer | 132.861 | 0.0 | 295.4 | 23 |
| 30 min Summer | 87.290 | 0.0 | 388.7 | 37 |
| 60 min Summer | 54.663 | 0.0 | 503.3 | 66 |
| 120 min Summer | 33.095 | 0.0 | 610.4 | 126 |
| 180 min Summer | 24.358 | 0.0 | 674.1 | 184 |
| 240 min Summer | 19.485 | 0.0 | 719.1 | 244 |
| 360 min Summer | 14.144 | 0.0 | 782.9 | 362 |
| 480 min Summer | 11.275 | 0.0 | 831.7 | 480 |
| 600 min Summer | 9.449 | 0.0 | 870.8 | 570 |
| 720 min Summer | 8.176 | 0.0 | 903.4 | 618 |
| 960 min Summer | 6.502 | 0.0 | 955.7 | 742 |
| 1440 min Summer | 4.700 | 0.0 | 1027.0 | 1008 |
| 2160 min Summer | 3.392 | 0.0 | 1138.2 | 1412 |
| 2880 min Summer | 2.689 | 0.0 | 1202.4 | 1824 |
| 4320 min Summer | 1.935 | 0.0 | 1295.9 | 2640 |
| 5760 min Summer | 1.531 | 0.0 | 1374.0 | 3456 |
| 7200 min Summer | 1.276 | 0.0 | 1430.6 | 4184 |
| 8640 min Summer | 1.099 | 0.0 | 1477.4 | 4920 |
| 10080 min Summer | 0.968 | 0.0 | 1515.9 | 5440 |
| 15 min Winter | 132.861 | 0.0 | 331.4 | 22 |
| 30 min Winter | 87.290 | 0.0 | 434.7 | 37 |

Summary of Results for 100 year Return Period (+40%)

| Storm Event | Max Level (m) | Max Depth (m) | Max Control (l/s) | Max Volume (m³) | Status |
|---|---|---|---|---|---|
| 60 min Winter | 100.773 | 0.773 | 8.0 | 552.6 | O K |
| 120 min Winter | 100.882 | 0.882 | 8.5 | 651.4 | O K |
| 180 min Winter | 100.934 | 0.934 | 8.8 | 700.6 | O K |
| 240 min Winter | 100.963 | 0.963 | 8.9 | 728.4 | O K |
| 360 min Winter | 100.990 | 0.990 | 9.0 | 754.4 | O K |
| 480 min Winter | 100.999 | 0.999 | 9.1 | 763.8 | O K |
| 600 min Winter | 100.999 | 0.999 | 9.1 | 763.1 | O K |
| 720 min Winter | 100.992 | 0.992 | 9.1 | 756.4 | O K |
| 960 min Winter | 100.971 | 0.971 | 9.0 | 736.4 | O K |
| 1440 min Winter | 100.930 | 0.930 | 8.8 | 696.5 | O K |
| 2160 min Winter | 100.856 | 0.856 | 8.4 | 627.5 | O K |
| 2880 min Winter | 100.781 | 0.781 | 8.0 | 559.7 | O K |
| 4320 min Winter | 100.638 | 0.638 | 7.6 | 437.7 | O K |
| 5760 min Winter | 100.500 | 0.500 | 7.6 | 327.8 | O K |
| 7200 min Winter | 100.322 | 0.322 | 7.6 | 199.0 | O K |
| 8640 min Winter | 100.209 | 0.209 | 7.6 | 124.1 | O K |
| 10080 min Winter | 100.177 | 0.177 | 6.9 | 103.6 | O K |

| Storm Event | Rain (mm/hr) | Flooded Volume (m³) | Discharge Volume (m³) | Time-Peak (mins) |
|---|---|---|---|---|
| 60 min Winter | 54.663 | 0.0 | 564.3 | 66 |
| 120 min Winter | 33.095 | 0.0 | 684.1 | 124 |
| 180 min Winter | 24.358 | 0.0 | 755.4 | 182 |
| 240 min Winter | 19.485 | 0.0 | 805.6 | 240 |
| 360 min Winter | 14.144 | 0.0 | 876.8 | 354 |
| 480 min Winter | 11.275 | 0.0 | 931.2 | 466 |
| 600 min Winter | 9.449 | 0.0 | 974.5 | 576 |
| 720 min Winter | 8.176 | 0.0 | 1010.5 | 680 |
| 960 min Winter | 6.502 | 0.0 | 1067.4 | 776 |
| 1440 min Winter | 4.700 | 0.0 | 1136.3 | 1082 |
| 2160 min Winter | 3.392 | 0.0 | 1275.2 | 1536 |
| 2880 min Winter | 2.689 | 0.0 | 1347.2 | 1988 |
| 4320 min Winter | 1.935 | 0.0 | 1451.7 | 2848 |
| 5760 min Winter | 1.531 | 0.0 | 1539.4 | 3688 |
| 7200 min Winter | 1.276 | 0.0 | 1602.9 | 4328 |
| 8640 min Winter | 1.099 | 0.0 | 1655.6 | 4664 |
| 10080 min Winter | 0.968 | 0.0 | 1699.3 | 5248 |

## Rainfall Details

| | | | |
|---|---|---|---|
| Rainfall Model | FSR | Winter Storms | Yes |
| Return Period (years) | 100 | Cv (Summer) | 0.750 |
| Region | England and Wales | Cv (Winter) | 0.840 |
| M5-60 (mm) | 19.300 | Shortest Storm (mins) | 15 |
| Ratio R | 0.400 | Longest Storm (mins) | 10080 |
| Summer Storms | Yes | Climate Change % | +40 |

## Time Area Diagram

Total Area (ha) 1.250

| Time (mins) From: | To: | Area (ha) | Time (mins) From: | To: | Area (ha) |
|---|---|---|---|---|---|
| 0 | 4 | 0.625 | 4 | 8 | 0.625 |

## Model Details

Storage is Online Cover Level (m) 101.300

## Tank or Pond Structure

Invert Level (m) 100.000

| Depth (m) | Area (m²) | Depth (m) | Area (m²) | Depth (m) | Area (m²) | Depth (m) | Area (m²) |
|---|---|---|---|---|---|---|---|
| 0.000 | 548.0 | 0.700 | 850.9 | 1.400 | 1110.5 | 2.100 | 1110.5 |
| 0.100 | 591.5 | 0.800 | 894.4 | 1.500 | 1110.5 | 2.200 | 1110.5 |
| 0.200 | 634.9 | 0.900 | 938.1 | 1.600 | 1110.5 | 2.300 | 1110.5 |
| 0.300 | 677.9 | 1.000 | 981.1 | 1.700 | 1110.5 | 2.400 | 1110.5 |
| 0.400 | 721.2 | 1.100 | 1024.2 | 1.800 | 1110.5 | 2.500 | 1110.5 |
| 0.500 | 764.8 | 1.200 | 1067.4 | 1.900 | 1110.5 | | |
| 0.600 | 808.0 | 1.300 | 1110.5 | 2.000 | 1110.5 | | |

## Hydro-Brake® Outflow Control

Design Head (m) 1.000 Hydro-Brake® Type Md4 Invert Level (m) 100.000
Design Flow (l/s) 9.1 Diameter (mm) 108

| Depth (m) | Flow (l/s) | Depth (m) | Flow (l/s) | Depth (m) | Flow (l/s) | Depth (m) | Flow (l/s) |
|---|---|---|---|---|---|---|---|
| 0.100 | 3.2 | 1.200 | 10.0 | 3.000 | 15.7 | 7.000 | 24.0 |
| 0.200 | 7.5 | 1.400 | 10.8 | 3.500 | 17.0 | 7.500 | 24.9 |
| 0.300 | 7.0 | 1.600 | 11.5 | 4.000 | 18.2 | 8.000 | 25.7 |
| 0.400 | 6.3 | 1.800 | 12.2 | 4.500 | 19.3 | 8.500 | 26.5 |
| 0.500 | 6.6 | 2.000 | 12.9 | 5.000 | 20.3 | 9.000 | 27.3 |
| 0.600 | 7.1 | 2.200 | 13.5 | 5.500 | 21.3 | 9.500 | 28.0 |
| 0.800 | 8.1 | 2.400 | 14.1 | 6.000 | 22.3 | | |
| 1.000 | 9.1 | 2.600 | 14.7 | 6.500 | 23.2 | | |